

# BoltLinx Glide Linking Table Legs

## Install Instructions

### Tools Required

- #2 Phillips Head 
- Drill 

### Hardware Included

- 8 - Flat Head Screw (2 per leg) 

### Installation

1. Lay out protective floor covering (cardboard, blanket, etc.)
2. Lay table on protective floor covering so the bottom of the table is facing up.
3. Locate the **FRONT** and **BACK** of the table (Figure A).
4. Notice that the **BACK** legs have a greater angle to the table than the **FRONT** legs do.
5. Locate the 8 holes where the legs will be attached.
6. Using the drill, secure the front legs to the front of the table with the flat head screws provided (Figure B).
7. Using the drill, secure the back legs to the back of the table with the flat head screws provided (Figure C).
8. Once all screws are securely tightened, the table can be flipped up-right (Figure D).
9. If installing BoltLinx on a corner table, install standard glide link in the center. (Figure E).

Figure A




Figure B




Figure C




Figure D




Figure E

