

MagLinx™ Glide Linking Table Legs

Install Instructions

Tools Required

- #2 Phillips Head 
- Drill 

Hardware Included

- 8 - Flat Head Screw (2 per leg) 

Installation

1. Lay out protective floor covering (cardboard, blanket, etc.)
2. Lay table on protective floor covering so the bottom of the table is facing up.
3. Locate the **FRONT** and **BACK** of the table (Figure A).
4. Notice that the **BACK** legs have a greater angle to the table than the **FRONT** legs do.
5. Locate the 8 holes where the legs will be attached.
6. Using the drill, secure the **Male** front leg and the **Female** front legs to the front of the table with the flat head screws provided (Figure B).
7. Ensure that the **Male** front leg is on the **MALE SIDE** and that the **Female** front leg is on the **FEMALE SIDE**.
8. Using the drill, secure the **Male** back leg and the **Female** back legs to the back of the table with the flat head screws provided (Figure C).
9. Ensure that the **Male** back leg is on the **MALE SIDE** and that the **Female** back leg is on the **FEMALE SIDE**.
10. Once all screws are securely tightened, the table can be flipped up-right (Figure D).
11. If installing MagLinx™ on a corner table, install standard glide link in the center. (Figure E).
12. Ref. [MagLinx™ Usage Instructions](#)

Figure A




Figure B




Figure C




Figure D




Figure E

