

# Vision-END WITH ANGLE BRACKETS

## Install Instructions

### Recommended Tools



### Hardware Included

- Screws to attach support and 45deg. supports

### Installation

Note: Use predrilled hole to locate support

1. Table upside down on clean surface.
2. Determine the mounting location of support. (Figure A)
3. Attached with screw provided
4. Attach the 45 deg supports in predrill holes (Figure B)
5. Make sure end support is 90 deg to the top when attached.

Figure A





Figure B



Failure to comply with installation instructions will compromise the safety, durability and performance of this product, which may risk injury to the user of this product and/or diminish the product life cycle. Jasper Group assumes no liability in these instances.